



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Ali'i Dr03rpt-spp.doc*

1. Project Name: Alii Drive SPP
2. Date of Inspection: May 23, 2003
3. Inspection Personnel:

Name	Agency/Office	Telephone No.
a. Dan Meyers	CEPOH-EC-T	808-438-8875
b. Rick Oleniczak	CEPOH-EM	808-438-1981
c. Randy Riley	DPW	808-322-2877

4. Discussion:

The project, completed in January 2000, provided for the repairs of a 705 LF seawall with grout bags to fill / repair the voids along the toe of the structure. Mr. Randy Riley, the DPW representative attended this inspection. Baseline photographs, deficiencies and suggestions are listed below.



- a. Sta. 0+00, Overview of the project (reference photo).



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Ali'I Dr03rpt-spp.doc*



b. Sta. 0+25, Typical grout bags (reference photo).



c. Sta. 1+00, Monitor the crest separation. This is an existing condition (reference photo). Repairs have been made.





**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Ali'I Dr03rpt-spp.doc*



d. Sta. 1+75, Typical grout bag placement (reference photo).



e. Sta. 2+10, Monitor the dislocated armor toe stone in this area.





**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Ali'I Dr03rpt-spp.doc*



f. Sta. 2+26, Historical Landmark, "Pa O Umi" , no work within 5 feet either side (reference photo).



g. Sta. 2+26, Monitor this area for movement, 1 ea. dislocated grout bag.





**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Ali'I Dr03rpt-spp.doc*



h. Sta. 3+35, Overview (reference photo).



i. Sta. 5+50, High wave energy area, (reference photo).



**CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT**  
**FOR HURRICANE & SHORE PROTECTION PROJECTS**  
Honolulu Engineer District  
CEPOH-EC-T

*Ali'I Dr03rpt-spp.doc*



j. Sta. 7+05, Overview (reference photo).

5. Findings/Conclusions:

IAW ER 500-1-1, ( dtd 30 September 2001 ), and based on this CEI, the Project is rated SATISFACTORY , Project Condition Code is ACCEPTABLE and the project is considered ACTIVE.

Signed: \_\_\_\_\_  
Dan Meyers, CEPOH-EC-T

Signed: \_\_\_\_\_  
James Pennaz, P.E., CH, CEPOH-EC-T